








# PCI TR-31 Encryption Keypad Requirement

## Hyosung ATMs

MODEL	CORE VERSION	KEYPAD VERSION	ACTION
 MBxxxx			replace ATM
 1500CE			replace ATM
 1500SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 1800 / CE			replace ATM
 1800SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 2100T			replace ATM
 2600SE Halo & Halo II		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 2700 / T		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 2700SE / T Force		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 4000W		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5000CE / 5050CE			replace ATM
 5000SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5000XP			replace ATM
 5100 / T	852, 945, G41		replace ATM
	H81, Q87, Q170, SBC210	3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5200SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 (MX)5200		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5300CE			replace ATM
 5300SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5300XP	852, 945, G41		replace ATM
	H81, Q87, Q170, SBC210	3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5400SE		3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 5600 / T	852, 945, G41		replace ATM
	H81, Q87, Q170, SBC210	3000, 5000, 6000	replace keypad and update software
		8000, X1	update software
 7000D			replace ATM



A Partnership You Can Count On

1-800-550-5087 | sales@atmusa.com | www.atmusa.com