












PCI TR-31 Encryption Keypad Requirement

Triton ATMs

MODEL	KEYPAD VERSION	ACTION
 8100		replace ATM
 9100		replace ATM
 9600		replace ATM
 9700		replace ATM
 RL1600	up to T9	replace keypad and update software
	T10	update software
 RL2000	up to T9	replace keypad and update software
	T10	update software
 RT2000	up to T9	replace keypad and update software
	T10	update software
 RL5000	up to T9	replace keypad and update software
	T10	update software
 FT5000	up to T9	replace keypad and update software
	T10	update software
 ARGO / FT RL6000 RL7000	up to T9	replace keypad and update software
	T10	update software
 TRAVERSE RL3000	up to T9	replace keypad and update software
	T10	update software



A **Partnership** You Can Count On

1-800-550-5087 | sales@atmusa.com | www.atmusa.com